

## **\*\*IMPORTANT NOTICE\*\***

**Ensure that the front panel INPUT setting is set correctly to match the input jack being used.**

**An incorrect setting will not damage the Atlas, but will result in severe distortion and other signal degradation.**